



A Burlington
Environmental Inc.
Company

CERTIFIED MAIL

January 19, 1990

W. Douglas Smith
U.S. EPA Region X
Air & Toxics Division - MS AT-093
1200 Sixth Avenue
Seattle, Washington 98101

Dear Mr. Smith:

During a recent telephone conversation with Tom King, Plant Supervisor at Chemical Processors' Georgetown facility (S. Lucile Street), you requested a copy of the 1988 Annual Summary of PCB Storage Activity. Please find enclosed, a copy of that report for your files.

Note: The weights tabulated are in kilograms as is required by TSCA regulations.

If you have any questions or comments concerning this summary, please contact me at 223-0500, extension 584.

Sincerely,

Trudy A. Harding
Compliance Specialist

TAH:tk

Enclosure

cc: D. L. Aubry - Georgetown
T. L. King - Georgetown
S. B. Donahue - Regulatory Affairs

CHEMICAL PROCESSORS, INC.

2203 Airport Way South . Suite 400 • Seattle, Washington 98134
(206) 223-0500 • FAX: 223-7791

CHEMICAL PROCESSORS INC.
GEORGETOWN FACILITY

Annual Summary of PCB Storage Activity
For the Year of:

1988

RECEIVED OR GENERATED:

XFMRS		BALLAST		OILS		RINSE		CONT. SOLIDS		CAPS	
#	Weight	#	Weight	#	Weight	#	Weight	#	Weight	#	Weight
.69		487	144;737.55	93	20570.85	40	7953.3	137	27637.6	8774	12498.

SHIPPED TO CSSI, ARLINGTON, OR

XFMRS		BALLAST		OILS		RINSE		CONT. SOLIDS		CAPS	
#	Weight	#	Weight	#	Weight	#	Weight	#	Weight	#	Weight
72		414	143543.25					115	20759		

SHIPPED TO ROLLINS, DEER PARK, TX:

XFMRS		BALLAST		OILS		RINSE		CONT. SOLIDS		CAPS	
#	Weight	#	Weight	#	Weight	#	Weight	#	Weight	#	Weight
				53	12487.5	28	6025.05	62	6428.25	5487	40047.

IN STORAGE LAST DAY OF YEAR:

XFMRS		BALLAST		OILS		RINSE		CONT. SOLIDS		CAPS	
#	Weight	#	Weight	#	Weight	#	Weight	#	Weight	#	Weight
		16	4881.6	48	9877.95	7	1928.25	81	14721.75	82	450

NOTE: Increase in contaminated solids is due to solidification of material.